MEMORANDUM:

TO: Jackie Prince, USEPA

FROM: Yee Cho, MA DEQE

DATE: June 12, 1985

RE: New Bedford Trip Report of June 5, 1985 to Files

New Rections



SDMS DocID 000226898

Thanks for a copy of your subject report. I have the following suggestions and changes to the report, as highlighted below:

West Side of the Acushnet River Estuary

- (2) Coffin St. Cove: (south side) Overgrown, industrial area, not easily accessible; fencing also not practicable due to lack of endpoints.

 (north side) Playground abutting the estuary in residential area close to a well-traveled street; #1 area for fencing (approx. 150-200 yards between two existing buildings (Mutterpie (sp?) Co. and Mars More Value, and for sign posting.
- (3) Side Streets/Company Driveways:

Coffin St.: open, but industrial, private area; emphasis on insuring limited access.

Cameo Curtain Co.: OK, NO SUGGESTED CHANGES.

Fiber Leather Co.: fence exists w/ gates, emphasis on closing gates on both sides.

Howard Ave./River Street: no existing fence, a residential area adjacent to vacant and grassed land area that borders the shoreline; fencing may not be feasible without identifiable endpoints for fence; options need to be examined; need bilingual signs.

Wood St. Bridge - North: easily accessible; need sampling to determine contamination levels.

East Side of the Acushnet River Estuary

area does not readily lend itself to fencing....

Lawson Avenue:Baiting activity noted by parked van and conversation with driver. Possibly an area to post signs in both English and Portuguese.....

Magnolia Ave.: private property; signs posted in area.

Recommendations (to supplement your 5/17/85 memo to MSH):

Priority #1: OK, NO SUGGESTED CHANGES

Priority #2: Examine options to limit access to the Howard Ave/River St. area; it is a residential area and the vacant land area is adjacent to the shoreline; it can be an inviting area for children's play.

Priority #3: identified as Priority #2 in your memo.

Priority #4: identified as Priority #3 in your memo.

Priority #5: Requests to several companies along the western shore to keep their gates closed (& construct gates if needed) whenever possible, and always after normal business hours.

Priority #6: Examine options for covering the exposed, highly contaminated shoreline mudflat area (e.g. with clean sediment, crushed stone and gravel, etc.), particularly in accessible areas in which fencing is not practicable.

cc. Paul T. Anderson, REE, DEQE- Lakeville James C. Colman, DSHW-Boston